FIRE HAZARD SEVERITY ZONE

FIRE HAZARD SEVERITY ZONE

FIRE HAZARD SEVERITY ZONE

OWNER: **TIMOTHY & SHERYL SCHEY** Pacific Palisades, Ca. 90272

CONSULTANTS: STRUCTURAL ENGINEER BEROZ & ASSOC., INC. 5530 Corbin Ave. Suite 359 Tarzana , Ca. 91356

PH: 818 668 - 8589 CIVIL ENGINEER <u>ADVANCED ENGINEERING</u> 22837 Ventura Bl., Suite 10

Woodland Hills , Ca. 91364 PH: 818 222 - 7982 GEOTECHNICAL ENGINEER :

BYER GEOTECHNICAL INC. 461 E. Chevy Chase Dr., Suite 200 Glendale . Ca. 91206 PH: 818 549 - 9959

ENERGY CALCULATIONS:

ALTERNATIVE ENERGY SYSTEMS 915 E. Tujunga Avenue Burbank . Ca. 91501 PH: 818 569 - 0243

707A.2 General. The following exterior covering materials and/or assemblies shall comply with this section:

FIRE HAZARD SEVERITY ZONE NOTES

5. Exposed underside of exterior porch ceilings

6. Exterior exposed underside of floor projections

1. Exterior wall architectural trim, embellishments,

3. Roof assembly projections over gable end walls

4. Solid wood rafter tails and solid wood blocking

installed between rafters having minimum dimen-

5. Deck walking surfaces shall comply with Section

2013 CALIFORNIA BUILDING CODE

NO. DATE ISSUANCE 11.21.14 IAS-BUILT PLAN 11.24.14 STUDY 1 . 01.08.15 STUDY 2 4. 01.09.15 STUDY 3 .| 01.13.15 |HOA REVIEW 7. 01.24.15 REVISIONS 8. 01.26.15 REVISIONS 0. 01.28.15 ENGINEER 0 01.28.15 HOA REVIEW 1 03.02.15 PLAN CHECK 12 04.30.15 VERIFICATION